

UIN 081D1EA

Diesel Engine

Unit No. Serena

Unit:
Make
Model
Serial No.
Site Eddie Reeves

Compartment:






Name Stbd Generator Engine
Make Northern Lights
Model
Serial No. 8434-45514C
Capacity: 0.0 Ltrs

Customer:
 TWO STAR MARITIME
 4725 Thornton Ave
 Fremont CA 94536
 USA

DIAGNOSIS

Engine wear levels appear satisfactory for first sample. Silicon level (dirt/sealant material) satisfactory. Water content acceptable. Viscosity within specified operating range. Action: Resample next service interval to monitor and establish wear trend.

ANALYST: Jon.Sowers

LEGEND				
				
Normal	Severe	Abnormal	Caution	Normal

DATE SAMPLED	24-Jul-20
DATE RECEIVED	25-Aug-20
DATE REPORTED	18-Sep-20
LAB NO.	42021538007
SIF NO.	25500773
TIME ON UNIT	4275
TIME ON OIL	75
OIL BRAND	Shell
OIL TYPE	Rotella T4 Tri P (CK4)
OIL GRADE	SAE 15W40
OIL ADDED	
FILTER	Not Applicable
OIL CHANGED	Not Provided
WO NUMBER	

Metals (ppm)

Iron (Fe)	6
Chromium (Cr)	<1
Lead (Pb)	<1
Copper (Cu)	<1
Tin (Sn)	3
Aluminium (Al)	<1
Nickel (Ni)	<1
Silver (Ag)	<1
Titanium (Ti)	<1
Vanadium (V)	<1

Contaminants (ppm)

Silicon (Si)	7
Sodium (Na)	2
Potassium (K)	5
Coolant	No

Additives (ppm)

Magnesium (Mg)	109
Calcium (Ca)	2233
Barium (Ba)	<1
Phosphorus (P)	1138
Zinc (Zn)	1339
Molybdenum (Mo)	11
Boron (B)	201

Contaminants

Water (%)	<0.05
-----------	-------

Physical Tests

Viscosity (cSt 100C)	15.0
Fuel (%)	<1
Soot (%) Infrared	0.3

Physical / Chemical

Base Number (mgKOH/g)	7.2
-----------------------	-----



UIN 081D1EA

U.S. Laboratories

- Atlanta, Georgia - 420**
5300 OakBrook Parkway
Building 200 Suite 245
Norcross, GA 30093
800.394.3669
- Valley View, Ohio - 410**
6180 Halle Dr. Suite D
Valley View, OH 44125
800.726.5400
- Kansas City, Kansas - 430**
935 Sunshine Road
Kansas City, KS 66115
800.332.8055
- Phoenix, Arizona - 440**
3319 West Earll Drive
Phoenix, AZ 85017
800.445.7930

Portland, Oregon - 401

4943 NW Front Avenue
Portland, OR 97210
800.770.4128

Canadian Laboratories

Burlington, Ontario - 450

5036 South Service Rd.
Burlington, ON L7L5Y7
905 332 9559

Edmonton, Alberta - 402

9450 17 Ave NW
Edmonton, AB T6N 1M9
888.489.0057

Sales & Marketing

Houston, Texas

10450 Stancliff Road, Suite 210
Houston, TX 77099
877.835.8437

International Locations

Australia

Brisbane, Perth, Sydney,
Muswellbrook

Europe

Prague

New Zealand






Wellington

South America

Santiago de Chile,
Belo Horizonte, Brazil

Southeast Asia

Kuala Lumpur, Singapore



Filter Image

Filter patch test is not performed Contact laboratory for more information

Since services are based on samples and information supplied by others, and since corrective actions, if any, are necessarily taken by others, these services are rendered without any warranty or liability of any kind beyond the actual amount paid to ALS Tribology for the services. Reported recommendations are based on interpretations of the generated test results and historical data. Certain test results appearing in this report may have been tested at other ALS laboratories within the Tribology divisional network.

Two Star Maritime
Attn: Ed
4725 Thornton Ave
Fremont CA 94536
USA